



DOM/ERW TUBING

A-500B: 20', 24', 40' & 48' LG

O.D	GAGE	WALL	I.D.	#/Ft	O.D	GAGE	WALL	I.D.	#/Ft	
1/2X	16	0.065	0.370	0.3020	2X	16	0.065	1.870	1.3430	
	14	0.083	0.334	0.3696		14	0.083	1.834	1.6990	
	12	0.109	0.282	0.4552		11	0.120	1.760	2.4090	
	11	0.120	0.260	0.4870		1/8	0.125	1.750	2.5030	
5/8X	16	0.065	0.495	0.3888		3/16	0.188	1.624	3.6380	
	14	0.083	0.459	0.4805		1/4	0.250	1.500	4.6730	
	12	0.109	0.407	0.6007		1/2	0.500	1.000	8.0100	
	11	0.120	0.385	0.6472		2 1/4X	2 1/4 X 3/16	0.188	1.874	4.1400
	10	0.134	0.357	0.7027			1/4	0.250	1.750	5.3400
				1/2			0.500	1.250	9.3450	
3/4X	16	0.065	0.620	0.4755		2 1/2X	2 1/2 X 14	0.083	2.334	2.1430
	14	0.083	0.584	0.5913			11	0.120	2.260	3.0500
	12	0.109	0.532	0.7462			3/16	0.188	2.124	4.6420
	11	0.120	0.510	0.8074			1/4	0.250	2.000	6.0080
1X	18	0.049	0.902	0.4977	1/2	0.500	1.500	10.6800		
	16	0.065	0.870	0.6491	3X	3 X 18	0.049	2.902	1.544	
	14	0.083	0.834	0.8129		16	0.065	2.870	2.0380	
	13	0.095	0.810	0.9182		14	0.083	2.834	2.5860	
	11	0.120	0.760	1.1280		11	0.120	2.760	3.6910	
	3/16	0.188	0.624	1.6300		3/16	0.188	2.624	5.6460	
1/4	0.250	0.500	2.0030	1/4		0.250	2.500	7.3430		
11/4X	11	0.120	1.010	1.4480	3/8	0.375	2.250	10.5100		
	3/16	0.188	0.874	2.1320	1/2	0.500	2.000	13.3500		
	1/4	0.250	0.750	2.6700	3 1/4X	3 1/4 X 1/4	0.250	2.750	8.0100	
	5/16	0.313	0.624	3.1320		1/2	0.500	2.250	14.6900	
11/2X	16	0.065	1.370	.9962	3 1/2X	3 1/2 X 11	0.120	3.260	4.3320	
	14	0.083	1.334	1.2560		3/16	0.188	3.124	6.6500	
	13	0.095	1.310	1.4260		1/4	0.250	3.000	8.6780	
	11	0.120	1.260	1.7690		3/8	0.375	2.750	12.5200	
	3/16	0.188	1.124	2.6340	4X	4 X 11	0.120	3.760	4.9730	
	1/4	0.250	1.000	3.3380		3/16	0.188	3.624	7.6540	
	5/16	0.313	0.874	3.9680		1/4	0.250	3.500	10.0100	
1/2	0.500	0.500	5.3400	3/8	0.375	3.250	14.5200			
13/4X	11	0.120	1.510	2.0890	1/2	0.500	3.000	18.6900		
	1/8	0.125	1.500	2.1690	4 1/4X	4 1/4 X 11	0.120	4.010	5.2930	
	10	0.134	1.482	2.3130		1/4	0.250	3.750	0.6800	
	1/4	0.250	1.250	4.0050						
	1/2	0.500	0.750	6.6750						

DON'T SEE IT ON THE LIST? CONTACT US!

6079 U.S. 50 West, Hillsboro, Ohio 45133
 (937) 402-7995 • Fax: (937) 393-15190 • dancefarmsupply@gmail.com